



## **KAK Industry – Lead Machinist**

The Lead Machinist for the KAK Industry Albany Missouri facility is responsible for conducting and managing the programming, setup, and operation of all machinery at the facility. The Lead Machinist reports directly to the Manufacturing Manager and may be responsible for other employees. The Lead Machinist is capable of carrying out all basic functions listed below and is expected to learn more advanced skills through additional training. Lead Machinist is a full-time hourly position with overtime available. All standard company benefits apply.

### General Responsibilities:

- Familiarity with all company policies and practices.
- Management of all assigned employees
- Setup and runoff of new or modified operations
- Operation of assigned machines and machine cells
- Fill in for Machine Operators when needed
- Ensuring consistent production through established quality control procedures
- Maintain an organized and clean work area
- Supervise and train assigned personell

### Requirements

- Five years experience operating, programming, and maintaining CNC machines
- Advanced knowledge of Fanuc CNC control systems
- Working knowledge of CNC programming
- Proven leadership ability
- Ability to lift and move 50 pounds
- Able to stand for the majority of a 10 hour shift
- Advanced knowledge of standard metrology instruments

### Work Week

- Rotating 10 hour shift – 4 days on, 2 days off, 3 days on, 3 days off
- Shifts are 5:00am to 3:30pm and 3:00pm to 1:30am
- Administrative shift is Monday through Friday 8:00am to 4:30pm
- Overtime may be required on occasion
- All times may be adjusted based on need